It seems that every peace of hardware I have needs a separate page. When I first bought it, I didn't have any problems with it.

Since then, <u>some kernels have problems with USB suspend</u>, but following works:

```
apt-get install cups splix
```

And then select ML-2150 in cups.

toner

- http://rumburg.org/printerhack/
- http://www.arbikas.com/yabbfiles/Attachments/ML1640_reset.pdf
- http://www.fixyourownprinter.com/forums/laser/44978 (it has i2c eeprom and fuse)